

## INTERSECTION TRAFFIC CONTROL RECOMMENDATIONS

<u>Description</u>	<u>Major Street</u>	<u>Intersection Layout</u>	<u>Recommended Stop Condition</u>	<u>Accident History</u>	<u>Traffic Volume Content</u>
Madison Ave/Monroe St	Monroe St	Four Way	Four-way stop	Not met	Not-met
Lincoln Ave/ Monroe St	Monroe St	Four Way	Four-way stop	Not met	Not met
Lincoln Ave/Broad St	Lincoln Ave	Four way	Two-way stop on Broad St	Not met	Not met

### Madison Ave/Monroe St

The signal warrants at this intersection are not met. Traffic volumes are low and fairly equal on all for approaches of the intersection. A four-way stop is recommended at the intersection. This signal was previously recommended for removal in the BMTS November 2003 Village of Endicott Traffic Operations Study.

### Lincoln Ave/Monroe St

The signal warrants at this intersection are not met. Traffic volumes are low and fairly equal on all for approaches of the intersection. A four-way stop is recommended at the intersection. This signal was previously recommended for removal in the BMTS November 2003 Village of Endicott Traffic Operations Study.

### Lincoln Ave/Broad St

The signal warrants at this intersection are not met. There was a pedestrian accident at the intersection during the time period studies. Signal removal is recommended with a two-way stop with stop signs on Broad St. and improved pavement markings. This signal was previously recommended for removal in the BMTS November 2003 Village of Endicott Traffic Operations Study.